

Date 29.03.16

Valuation

V-16108

Machine type:	Mini excavator
Brand:	Hyundai
Type:	R35Z-9
Location:	66916 Breitenbach, Germany
Inspection date:	28.03.2016

Index of Contents:

1. Boundary condition
2. Documents
3. Machine dates and equipment
4. Technical inspection
5. Market value
6. Final remark
7. Photos

Date 29.03.16

1. Boundary condition

1.1 Order

According order of 26.03.2016 the technical condition of the excavator was inspected and a valuation was prepared.

The technical dates were taken from the documents of the excavator and and amended from plates of the machine.

1.2 Area condition during inspection

The machine was on a side road during inspection.
Rainy condition, a meaningful inspection was possible.

1.3 Damage before

No damage before is known or apparent.

2. Documents

2.1 Documents inside

- EC certificate of conformity
- Delivery receipt
- Brochure

Date 29.03.16

3. Machine dates and equipment

Type of vehicle: Mini excavator
Brand: Hyundai
Type: R35Z-9
Vehicle-Id-No.: HHKHMH03TE0000693
Year of manufacture: 2014
Working hours: 812,8
Weight: 3.750 kg
Engine: Yanmar 3TNv88 / 19,8 KW
Drive: Rubber
Chain profile: 80-90%
Track drive: 80-90%
Quick release MS 03
Arm 1600 mm
Hammer and grab pipe
Dozer blad
Overload warning device
Air condition, spring loaded seat
Without bucket

4. Inspection

The excavator was in good condition during the inspection.

All function were working, test run of the engine was without abnormal noise or smoke.
No leakage was available, bearing shake was not visible.

Small wear of painting at carrier, chain and track drive is according the working hours in normal range.

Date 29.03.16

5. Market value

In cause of the actually market situation and the good technical conditions of the machine, the estimated market value is

25.500 Euro excl. VAT

6. Final remark

The expertise is made as exactly as possible according the condition at the inspection area and the assistance of the operator. Our liability is excluded from all claims of any nature, especially for any defects which have not been found or any defects after the inspection.

This document is prepared with electronic devices and valid without signature.

Date 29.03.16

7. Photos



Date 29.03.16



Date 29.03.16

